David Taylor Research Center


Bethesda, Maryland 20084-5000

DTRC-SME-89/45 March 1990

Ship Materials Engineering
Research and Development Report

Defect Area Determination of Organic Coated Steels in Seawater Using the Breakpoint Frequency Method

by Harvey P. Hack John R. Scully





Approved for public release; distribution unlimited

MAJOR DTRC TECHNICAL COMPONENTS

- CODE 011 DIRECTOR OF TECHNOLOGY, PLANS AND ASSESSMENT
 - 12 SHIP SYSTEMS INTEGRATION DEPARTMENT
 - 14 SHIP ELECTROMAGNETIC SIGNATURES DEPARTMENT
 - 15 SHIP HYDROMECHANICS DEPARTMENT
 - 16 AVIATION DEPARTMENT
 - 17 SHIP STRUCTURES AND PROTECTION DEPARTMENT
 - 18 COMPUTATION, MATHEMATICS & LOGISTICS DEPARTMENT
 - 19 SHIP ACOUSTICS DEPARTMENT
 - 27 PROPULSION AND AUXILIARY SYSTEMS DEPARTMENT
 - 28 SHIP MATERIALS ENGINEERING DEPARTMENT

DTRC ISSUES THREE TYPES OF REPORTS:

- 1. **DTRC reports, a formal series,** contain information of permanent technical value. They carry a consecutive numerical identification regardless of their classification or the originating department.
- 2. **Departmental reports, a semiformal series,** contain information of a preliminary, temporary, or proprietary nature or of limited interest or significance. They carry a departmental alphanumerical identification.
- 3. **Technical memoranda, an informal series,** contain technical documentation of limited use and interest. They are primarily working papers intended for internal use. They carry an identifying number which indicates their type and the numerical code of the originating department. Any distribution outside DTRC must be approved by the head of the originating department on a case-by-case basis.


REPORT (OCUMENTATIO	N PAGE			Form Approved OMB No 0704-0188
1a REPORT SECURITY CLASSIFICATION Unclassified		16 RESTRICTIVE	MARKINGS		
2a SECURITY CLASSIFICATION AUTHORITY		3 DISTRIBUTION	V · AVAILABILITY C	F REPOR	ĭ
26 DECLASSIFICATION DOWNGRADING SCHEDU	LE	see :	reverse sid	e	
4 PERFORMING ORGANIZATION REPORT NUMBE DTRC-SME-89/45	R(S)	5 MONITORING	ORGANIZATION I	REPORT N	iumber(S)
6a NAME OF PERFORMING ORGANIZATION	6b OFFICE SYMBOL (If applicable)	7a NAME OF N	ONITORING ORGA	ANIZATIOI	N
David Taylor Research Center	Code 2813				
Bethesda, MD. 20084-5000		7b ADDRESS (C	ity, State, and ZIP	Code)	
8a NAME OF FUNDING/SPONSORING ORGANIZATION	8b OFFICE SYMBOL (If applicable)	9 PROCUREMEN	IT INSTRUMENT IS	DENTIFICA	TION NUMBER
Naval Civil Engineering Lab	L52				
8c ADDRESS (City, State, and ZIP Code)		10 SOURCE OF	FUNDING NUMBE	RS TASK	WORK UNIT
		ELEMENT NO	NO	NO	ACCESSION NO
Port Hueneme, CA	·	<u> </u>	<u> </u>		
11 TITLE (Include Security Classification) Defect Area Determination of	Organic Coated	Stools in S	Sommetor He	ina th	
Breakpoint Frequency Method	organic coated	Steers in .	seawater us	Ing th	
12 PERSONAL AUTHOR(S)					
Harvey P. Hack and John R. S					
13a TYPE OF REPORT 13b TIME C		14 DATE OF REPO		, Day)	5 PAGE COUNT 36
R&D FROM		March 199	111		
	18 SUBJECT TERMS			al aloneit	. h., block number)
17 COSATI CODES FIELD GROUP SUB-GROUP	18 SOBJECT TEKNIS	Continue on rever	se ir necessary ar	id identiti)	y by block number)
3/05 3/05					$Y_{i,j}$
	1 july 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		<u> </u>	<u> </u>	1 (j e)
19 ABSTRACT (Continue on reverse if necessary					
`Coating breakdown is a majo		-			
have a rapid technique for pr					
A method for simply determini	ng the extent	of coating b	oreakdown w	ould t	herefore be of
great use to the Navy.			11 1-4		
The breakpoint frequency me					
chemically active area of a c explain the basis of the brea					
visual data from epoxy coated	-		•		-
an intentional defect of know		1. /			;
The breakpoint frequency me	•	to be extre	emely usefu	l in d	etermining the
electrochemically active area	of coated stee	el in seawat	er. The eq	uivale	nt circuit model
used in this analysis was fou	nd capable of	fitting actu	ual data in	coate	d steel panels
20 DISTRIBUTION AVAILABILITY OF ABSTRACT		21 ARSTRACT S	ECURITY CLASSIFI	CATION	
UNCLASSIFIED: UNLIMITED SAME AS I	RPT DTIC USERS	linclass	ified		
228 NAME OF RESPONSIBLE INDIVIDUAL		226 TELEPHONE (301) 26	(Include Area Coo		OFFICE SYMBOL Code 2813

(Block 3)

Distribution authorized to U.S. government agencies only; research and development, October 1989. Other requests for this document shall be referred to the Naval Civil Engineering Laboratory (Code L52) Port Hueneme, CA 93043

(Block 19 Continued)

with and without an intentional defect. A correlation was obtained between the breakpoint frequency and visually estimated electrochemically active area on epoxy coatings of a variety of thicknesses. This method offers a simple alternative to determination of defect areas via the use of the pseudocapacitance from difficult-to-analyze low frequency impedance data. This approach also can detect the beginnings of coating breakdown long before visual indications are present.



CONTENTS

		Page
ABST	RACT	1
ADMI	NISTRATIVE INFORMATION	1
INTR	ODUCTION	2
EXPE	RIMENTAL	10
THE I	BREAKPOINT FREQUENCY METHOD	4
EXPE	RIMENTAL APPROACH	11
RESU	LTS AND DISCUSSION	14
<u>M</u>	odeling	14
<u>R</u>	elationship Between Breakpoint Frequency	
	and Exposure Time	18
CONC	LUSIONS	29
ACKN(OWLEDGEMENTS	29
REFE	RENCES	30
	FIGURES	
1.	Nested simplified randles circuit of a coated steel panel with a defect	4
2.	Effect of defect area percentage on impedance magnitude behavior of a coated steel equivalent circuit. Total cell area assumed is 10 cm ²	6
3.	Effect of defect area percentage on impedance phase behavior of a coated steel equivalent circuit. Total cell area assumed is 10 cm ²	7
4.	Defect area percentages for 0-10 rating system for ASTM standard d-610 and modified d-714	13
5.	Impedance magnitude data for a transparent epoxy coating on steel in ASTM seawater. Solid lines	

	are fit from equivalent circuit model	•	•	•	•	•	15
6.	Impedance phase data for a transparent epoxy coating on steel in ASTM seawater. Solid lines are fit from equivalent circuit model		•				16
7.	Equivalent circuit components used for curves in Figs. 5 and 6	•	•			•	17
8.	25 µm thick epoxy coating on steel after various exposure times in seawater. (Area 13.13 cm ²)	•	•		•		19
9.	55 µm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm ²).	•	•		•	•	20
10.	116 µm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm ²).	•	•	•			21
11.	155 μm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm ²).		•	•		•	22
12.	Increase in the higher breakpoint frequency with exposure time for 55 µm thick epoxy coated steel in ASTM seawater. (Area 13.13 cm ²)	•	•	•	•		25
13.	Increase in the higher breakpoint frequency with exposure time for 116 μm thick epoxy coated steel in ASTM seawater. (Area 13.13 cm ²)	•	•	•	•	•	26
14.	Relationship between breakpoint frequency and estimated electrochemically active area for opaque and transparent epoxy coatings on steel. (Solid lines have been added to aid the reader).						27

ABSTRACT

Coating breakdown is a major maintenance cost on ships. It is therefore desireable to have a rapid technique for predicting or evaluating coating performance non-destructively. A method for simply determining the extent of coating breakdown would therefore be of great use to the Navy.

The breakpoint frequency method is described which allows determination of the electrochemically active area of a coated metal in seawater. A computer model is used to explain the basis of the breakpoint method, and the model is compared to impedance and visual data from epoxy coated steel panels in ASTM artificial seawater with and without an intentional defect of known area.

The breakpoint frequency method was found to be extremely useful in determining the electrochemically active area of coated steel in seawater. The equivalent circuit model used in this analysis was found capable of fitting actual data on coated steel panels with and without an intentional defect. A correlation was obtained between the breakpoint frequency and visually estimated electrochemically active area on epoxy coatings of a variety of thicknesses. This method offers a simple alternative to determination of defect areas via the use of the pseudocapacitance from difficult-to-analyze low frequency impedance data. This approach also can detect the beginnings of coating breakdown long before visual indications are present.

ADMINISTRATIVE INFORMATION

This project was supported by the DTRC Ship and Submarine Materials Block Program under the administration of DTRC Code 0115. The program coordinator is Mr. Ivan Caplan. The work described was performed under Work Unit 1-2813-959 and satisfies milestone CT6/4. The work was conducted at DTRC in the Marine Corrosion Branch, Code 2813, under the direction of Mr. Robert Ferrara.

INTRODUCTION

Coating breakdown is a major maintenance cost on ships. It is therefore desireable to have a rapid technique for predicting or evaluating coating performance non-destructively. A method for simply determining the extent of coating breakdown would therefore be of great use to the Navy.

A good organic coating will protect the steel beneath it except at blisters and holidays, and only at these defects will corrosion occur. Similarly, the high resistance of a good coating will cause the principal cathodic protection current demand to be determined from the defect areas. The area of coating defects is therefore important to know in order to determine corrosion rate from polarization data and to determine cathodic protection requirements. The percentage of defect area is also a good indication of coating quality and need for coating repair.

One possible method for determining the electrochemically active area under coating defects is by the use of interfacial capacitance measurements. This requires knowledge of specific capacitance (per unit area). In traditional aqueous electrochemistry, the double layer capacitance per unit area is usually considered similar to that for mercury, 15 to 30 µF/cm².[1,2] For corroding steel systems, "apparent" double layer capacitances are either found to be quite large (i.e. greater than 100 µF/cm²), difficult to calculate, or both.[3-6] For some corroding systems, sophisticated electrical equivalent circuit models have been used to determine the true interfacial capacitance, as it cannot readily be determined from raw impedance data.[7,6] In other

cases, an adsorption psuedo-capacitance model has led to determination of a capacitance which is larger than 30 $\mu F/cm^2.^{[6]}$ The electrochemically active area is determined from the following expression:

Area = Cmeas/Cspecific

where C_{meas} is the measured capacitance, in μF , using either of the appropriate methods discussed above, and $C_{s\,pec\,i\,f\,i\,c}$ is the area specific capacitance in $\mu F/cm^2$.

Using the above approach requires the selection of the proper specific capacitance, which is not always straightforward. Additional complexity is introduced for organic-coated steels because of the heterogeneity of the development of the electrochemical processes at the metal interface. Both perpendicular and tangential resistive paths in the coating have to be considered in electrical equivalent circuit modeling in addition to the interfacial processes. [9-12]

The purpose of this work was to evaluate a new approach to determining coating defect area which does not depend on rigorous analysis of lower frequency impedance data, as would be the case if coating resistance were to be determined. This approach, based on a technique discussed by Haruyama, et al. called the breakpoint method, uses high frequency data to obtain the electrochemically active area. [13] The breakpoint frequency method has been found to be more accurate than the specific capacitance method in soil corrosion work. [14] The correlation of the breakpoint frequency describing these

coating properties with defect area as determined by ASTM visual methods will be discussed.

THE BREAKPOINT FREQUENCY METHOD

One simple method used to model a good quality organic coating over steel in which a holiday exists is to use a nested, simplified Randles circuit as in Fig. 1. The bulk of the surface is covered with a coating with such high resistance as to be considered a pure capacitor, of value $C_{\rm c}$. The defect consists of a region extending completely through the coating thickness, d, that has a resistivity sufficiently lower than the




Fig. 1. Nested simplified randles circuit of a coated steel panel with a defect.

bulk ccaling to make electrochemical processes possible under that region. A defect could consist of a weak area of coating, or a crack or hole extending through the coating. This defect can be represented by its resistance through the coating thickness to the steel surface, Rd, in series with the parallel combination of a double layer capacitance (or interfacial pseudocapacitance), Cd1, and charge transfer resistance, Rt, associated with corrosion of the steel surface. The net impedance associated with the defect would be a function of defect area. In the modeling described below, Rd is assumed to have a resistivity similar to that of seawater, as though it were a hole filled with seawater, and Rt is assumed to be the same as for bare steel. Both of these assumptions are borne out to some extent by data shown below.

Varying the defect area percentage used with this equivalent circuit will lead to a family of curves, as shown in Figs. 2 and 3. These curves are for a total cell area of 10 cm² and defect area percentages as indicated. ASTM visual ratings for these same defect areas are also shown on the figures.

Breakpoint frequencies are shown on the Bode-Magnitude plot in Fig. 2 as the points where, descending the curve from higher to lower frequencies, a transition occurs from a capacitive region of slope = -1 to a resistive region of slope = 0. These same breakpoint frequencies are shown on a Bode-Phase plot in Fig. 3 as the points where, descending the curve from higher to lower frequencies, the phase shift first reaches 45 degrees.




Fig. 2. Effect of defect area percentage on impedance magnitude behavior of coated steel equivalent circuit. Total cell area assumed is $10\ \mathrm{cm}^2$.




Fig. 3. Effect of defect area percentage on impedance phase behavior of a coated steel equivalent circuit. Total cell area assumed is 10 cm2.

For larger defect area percentages, the point at which the coating impedance, $1/\omega C_c$, equals the defect resistance, R_d (plus the solution resistance, R_S , which is frequently negligible by comparison), is called the higher breakpoint frequency. This frequency, designated f_h following the notation of Haruyama, et al, [13] will be a direct function of the defect area percentage. The relationship between this breakpoint frequency and defect area is derived as follows:

$$R_d = 1/(2 \pi f_h C_c)$$
 $R_d = \rho d/A_d$ $C_c = \epsilon \epsilon_0 (A-A_d)/d$

where: $A_d = defect$ area

A = fixed total specimen area

ρ = intrinsic coating resistivity at defect

d = coating thickness

 ε = dielectric constant for the water-laden coating

 ε_{o} = permittivity of free space.

For defect areas of less than 1% of the sample area, $A-A_d$ is roughly equal to A and thus:

$$f_h = K A_d/A$$

where:
$$K = 1/(2 \pi \epsilon \epsilon_0 \rho)$$

A second, lower breakpoint frequency, designated f_1 again following the notation of Haruyama, et al, $^{[13]}$ will occur where the double layer impedance, $1/\mu C_{d,1}$, equals the charge transfer resistance, R_t , plus the defect resistance, R_d (plus the solution resistance, R_s , again negligible by comparison). This frequency can be derived as follows:

$$R_t + R_d = 1/(2 \pi f_1 C_{d_1})$$
 $R_d = 0 d/A_d$ $R_t = r_t/A_d$ $C_{d_1} = A_d C_{d_1}$

where: r: = unit area charge transfer resistance

Cd: = double-layer or pseudo- capacitance

 $c_{d\,l}$ = area specific double-layer or pseudo- capacitance

Thus: $f_1 = 1/\{2 \pi c_{d1} (\rho d + r_t)\}$

For practical coatings in seawater, ρ of the defect is on the order of 1-10 ohm-cm (bulk resistivity of good coatings is on the order of 10^{12} ohm-cm), r_t is on the order of 10^3 ohm-cm², and d is on the order of 10^{-2} cm. This makes ρ d roughly 4-5 orders of magnitude less than r_t and it can therefore be ignored. The equation then reduces to:

$$f_1 = 1/(2 \pi cd_1 rt)$$

This lower frequency is not dependent on defect area or cell area, but only on the relative magnitudes of the area specific double layer capacitance and charge transfer resistance of the defect.

Very small defect area percentages will lead to a situation where the defect resistance and double layer capacitance are not visible on the Bode-format figures due to poor separation of time constants. The higher breakpoint frequency, f_h , becomes unmeasurable, and the lower frequency, f_1 , becomes the frequency where the coating impedance, $1/\omega C_c$, equals the charge transfer resistance, R_1 , plus the defect resistance, R_2 (plus the solution resistance, R_3 , still negligible by comparison). This frequency is a direct function of defect area:

 $R_t+R_d = 1/(2 \pi f_1 C_c)$ $R_d = \rho d/A_d$ $R_t = r_t/A_d$ $C_c = \epsilon \epsilon_0 (A-A_d)/d$

Again assuming Ad < 1%:

$$f_1 = K' A_d/A$$

where: $K' = d/\{2 \pi \epsilon \epsilon_0 (\rho d + r_t)\}$

Again assuming that $\,\rho\,d$ is much less than r_t , the equation then reduces to:

$$f_1 = K' A_d/A$$

where: $K' = d/(2 \pi \epsilon \epsilon_0 r_t)$

This area dependence of the lower breakpoint frequency will only be seen when the coating is very good, such that the total double layer capacitance, $C_{d\,l}$, is less than the total coating capacitance, C_c . This will occur when:

$$C_{d1} < C_{c}$$
 where: $C_{d1} = A_{d} C_{d1}$ $C_{c} = \epsilon \epsilon_{o} (A-A_{d})/d$

or for $A_d < 1$ %: $A_d/A < \epsilon \epsilon_0 / c_{d,l} d$

While f_h will always depend on defect area, the above analysis shows that f_1 is only dependent on defect area for very small defects where f_h is not resolvable (Figs. 2 and 3). This is also the only condition under which a breakpoint frequency is dependent on coating thickness.

Assuming that ρ , ϵ , and r_t remain relatively constant, or that changes in ϵ are compensated for by changes in ρ or r_t to keep K or K' constant, the breakpoint frequencies can be monitored over time. This is probably realistic for the coatings tested herein after 30 days exposure. As the coating degrades with time, the defect area should grow and the breakpoint frequencies get larger. At early exposure times

when there are few or small defects, f_1 will be measured, but as the coating degrades, f_h will be the parameter determined during a scan from high frequencies to low frequencies.

The advantage of this method lies in its ability to obtain defect areas using the higher frequency part of the impedance spectra, without analyzing the complex behavior occurring at lower frequencies. In addition, a specific "bare metal" capacitance need not be used, with its associated uncertainties. The disadvantage is that during a measurement, it may not be immediately clear whether f; or fh is being measured. In practice, this is not a great disadvantage. Based on the model studies to date, the minimum value for a measurable fh is about 100 Hz whereas the maximum value for f; is about 10 Hz for the coatings and areas in this study. In practical systems, it is therefore usually possible to know which f is being measured simply by its value. An additional reason why this is not a problem is discussed below.

EXPERIMENTAL APPROACH

Cold rolled SAE 1010 1/4 hard steel panels (5 by 7 inches) with a 15-25 micro-inch ground surface were de-greased with xylene and coated with either opaque or transparent epoxy polyamides by a dip application method as in ASTM Standard D-823.^[15] The coatings were then allowed to cure fully. The opaque coatings were nominally defect free but may have contained microscopic latent discontinuities. Details for each coating type have been given elsewhere.^[10] Panels were exposed under freely corroding conditions in ASTM artificial ocean water at room temperature

with aeration provided by air bubbling (6 ppm dissolved oxygen concentration).

In one panel, an intentional defect of known area, 0.0066 cm², was created by drilling a small hole through a 70 µm transparent coating without penetrating the steel panel. Impedance data were collected on this panel with a cell placed over the defect after 3 hours exposure, and again with the cell over a different, undamaged area on the same panel after 24 hours exposure. At the time of the impedance measurement, the panel was momentarily removed from the seawater tank, and a cylindrical Lucite cell of 6.29 cm² area containing ASTM artificial ocean water was positioned on the panel surface. This cell contained a platinized screen auxiliary electrode oriented parallel to the painted metal surface. An aperture in the screen contained a glass-lined Ag/AgCl tipped reference electrode which was positioned between the painted surface and the counter electrode along the center line of the cylindrical cell. Impedance experiments were conducted using a Solartron 1250 frequency response analyzer, Stonehart BC 1200 potentiostat, and Tektronix 4052 computer. Impedance data were collected at frequencies ranging from 65 kHz downwards to 1 mHz.[10]

Occasionally during the exposure, each opaque panel was characterized by electrochemical impedance spectroscopy using a clamp-on cell similar to that described above but of 13.3 cm² area. Every few months, the panels were evaluated visually using ASTM Standard D-610^[16] for rust area, and a modification to D-714^[17] for blistering. These standards rate defective area on a scale of 0-10 as illustrated in Fig.

4. Defect area percentages less than 0.01% (ASTM 10 rating) are




Fig. 4. Defect area percentages for 0-10 rating system for ASTM standard D-610 and modified D-714.

not considered in this system. Visual ratings on transparent coatings were used in addition to opaque coatings in order to increase the level of confidence in the ASTM visual methods.

RESULTS AND DISCUSSION

Modeling

Impedance data from the transparent coated panel, both with and without the intentional defect, are presented in Figs. 5 and 6. A very low breakpoint frequency was observed for the defect-free sample with no corrosion visible at the coating-metal interface. A very high breakpoint frequency (greater than 65 khz) was observed for the test conducted over the defect. Since these measurements were made after 3 hours exposure, no delamination is assumed to have occurred under the coating adjacent to the bare metal. The intentional defect area of 0.0066 cm² can therefore be assumed to still be accurate.

Figure 7 shows the equivalent circuit model and specific resistances and capacitances that were used to model these data. The specific resistances and capacitances, and the "defect" area for the intact coating, were obtained by fitting to the data. The result was an equivalent circuit model in which only one parameter, coating defect area, could be changed to create the two solid curves in Figs. 5 and 6. This shows that the assumed model is capable of fitting data from coatings with intentional defects. The next logical experimental step, using a range of defect sizes, was not done due to the difficulty of accurately making defects smaller than 0.0066 cm². Larger defect sizes were not used as the frequency of 45 degree phase shift was already




Fig. 5. Impedance magnitude data for a transparent epoxy coating on steel in ASTM seawater. Solid lines are fit from equivalent circuit model.




Fig. 6. Impedance phase data for a transparent epoxy coating on steel in ASTM seawater. Solid lings are fit from equivalent circuit model.

"SPECIFIC" VALUE (ASSUMED TO GET DATA FIT)	A _{cell} = 6.29 cm ²	3.29 cm ²
	$A_d = 0.0066 cm^2$	$A_d = 3.2 \times 10^{-6} \text{ cm}^{2*}$
$c_c = 2 \times 10^{-9} \text{ F/cm}^2$	$C_C = 1.3 \times 10^{-8} \text{F}$	1.3 × 10 ⁻⁸ F
$R_S = 12 \Omega - cm^2$	$R_S = 2\Omega$	2 0
$r_{\rm t} = \frac{130 \ \Omega - cm^2}{A_d}$	$R_t = 2 \times 10^4 \Omega$	4 × 10 ⁷ Ω
$r_{d} = \frac{1.3 \Omega - cm^2}{A_d}$	$R_d = 200 \Omega$	4 × 10 ⁵ Ω
$c_{dl} = 1.3 \times 10^{-3} \text{ F/cm}^2 \times \text{Ad}$	$C_{dl} = 8.4 \times 10^{-6} F$	$4.2 \times 10^{-9} \mathrm{F}$

* FOR INTACT COATING, ASSUMED TO GET PROPER FIT

Fig. 7. Equivalent circuit components used for curves in Figs. 5 and 6.

larger than the maximum frequency of the transfer function analyzer used in gathering the data.

The difficulty in determining whether it is f₁ or f_b that is being measured can be seen to not be such a great disadvantage when inspecting Figs. 5 and 6. A coating is considered bad for marine service if it has large defects, typically larger than in these figures. Under these conditions, f_b is being measured all of the time. Thus if the breakpoint frequency exceeds the level predetermined as being "too many defects", f_b will always be the measured quantity. A better coating, with a lower breakpoint frequency, may still suffer the ambiguity, but this will be irrelevant in practice, since the coating is likely to be acceptable from a practical standpoint. Also, as mentioned earlier, there is a range of breakpoint frequencies that theoretically will not be measured, although in practice these frequencies are seen.

Comparison of ASTM ratings and defect area percentages from breakpoint frequency measurements in Figs. 2, 3, 5, and 6 show that the breakpoint frequency method can show differences in coating performance even for coatings with ASTM visual ratings that have not fallen below 10. This is therefore a very sensitive and useful technique for studying the early stages of coating breakdown.

Relationship Between Breakpoint Frequency and Exposure Time

Figures 8 to 11 illustrate the behavior of 25, 55, 116, and 155 µm thick opaque epoxy polyamide coatings on steel, respectively. From these figures the difficulty in extracting capacitance data can be seen, since high enough frequencies cannot be reached to obtain a segment of




Fig. 8. 25 μm thick epoxy coating on steel after various exposure times in seawater. (Area 13.13 cm²).




Fig. 9. 55 μm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm²).




Fig. 10. 116 µm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm²).




Fig. 11. 155 µm thick epoxy coating on steel after various exposure times in ASTM seawater. (Area 13.13 cm²).


curve with -1 slope. This is contrasted to the ease in determining the breakpoint frequency. The 25 µm thick coatings displayed evidence of corrosion within several days, and their breakpoint frequency is greater than 65 Khz at all exposure times. The 55 µm coating exhibited breakpoint frequency increases from about 10⁴ Hz at day one to over 65 kHz by 558 days. The 155 µm thick coating showed an increase in the breakpoint frequency which was accelerated over 21 days by cathodic polarization. The 25 and 55 µm thick coatings had greater breakpoint frequencies at all times than the 116 and 155 µm thick coatings, consistent with the greater amount of corrosion and blistering observed. In all cases the frequency associated with the 45 degree phase angle increases with exposure time, as shown in Figs. 12 and 13 for two replicate 55 µm and 155 µm thick coatings, respectively. The ASTM visual ratings are also shown on these plots. Good correlation between visual corrosion and the breakpoint frequency is observed.

Figure 14 shows the relationship between breakpoint frequency and estimated active area for both opaque and transparent coatings. The solid lines outline the scatterband for the data, with the expected slope of 1 for a proper correlation. The same trend is observed for the transparent coatings as for the opaque coatings. A breakpoint frequency greater than 10⁴ Hz indicates an active area equal to or greater than about 0.01%. A frequency less than 10² Hz indicates an active area equal to or less than about 0.0001%. The large amount of scatter in the data could be due to the uncertainties associated with estimating active area by visual means. Rust staining on the transparent coatings may remain visible even after corrosion has subsided, contributing to the


data scatter. Other methods for estimating active area such as acoustic or infra-red microscopy may prove more accurate.

Two-electrode measurements

The impedances involved on the coated surfaces are much higher than those of some counter electrodes. A two-electrode impedance measurement without a reference electrode measures the sum of counter and working electrode impedances. When the counter electrode impedance is negligible compared to that of the working electrode, these two techniques give the same results. Thus, a two-electrode system could be used for coating measurements, making the use of a potentiostat unnecessary. This would allow the measurement frequency to be extended well above the 65 Khz used in this study, increasing accuracy for large defect sizes.



Increase in the higher breakpoint frequency with exposure time for $55~\mu m$ thick epoxy coated steel in ASTM seawater. (Area $13.13~cm^2$). Fig. 12.



Increase in the higher breakpoint frequency with exposure time for 116 μ m thick epoxy coated steel in ASTM seawater. (Area 13.13 μ m²). Fig. 13.




Fig. 14. Relationship between breakpoint frequency and estimated electrochemically active area for opaque and transparent epoxy coatings on steel. (Solid lines have been added to aid the reader)

BREAKPOINT FREQUENCY,

CONCLUSIONS

The purpose of this work was to evaluate the breakpoint frequency approach to determining coating defect area for use by the Navy for ship coating systems. This method was found to be extremely useful in this regard.

The equivalent circuit model used in the breakpoint frequency analysis is capable of fitting actual data on coated steel panels with and without an intentional defect. A correlation was obtained between the breakpoint frequency and visually estimated electrochemically active area on epoxy coatings of a variety of thicknesses. This approach offers a simple alternative to determination of defect areas via the use of the pseudocapacitance from difficult to analyze low frequency impedance data. This approach also can detect the beginnings of coating breakdown long before visual indications are present. A simple two-electrode setup without a potentiostat could be used over a larger range of frequencies to generate more accurate information for larger defect sizes.

ACKNOWLEDGEMENTS

The authors would like to thank Dr. John Murray for his useful insights and his review of this manuscript. Bryan Pearce is also acknowledged for technician support. The coated panels used were provided by Dr. George Loeb and Dr. James Mihm.

REFERENCES

- 1. Lawrence J., R. Parsons and R. Payne, <u>J. Electroanal. Chem.</u>, <u>16</u>, 193 (1968).
- 2. Grahame, D.C. and B.A. Soderburg, J. Chem. Physics, 22, 449 (1954).
- 3. Scully, J.R. and K.J. Bundy, NACE CORROSION/83, Paper No. 253 (1983).
- 4. Murray, J.N., J. R. Scully, and P. J. Moran, NACE CORROSION/86, Paper No. 271 (1986).
- 5. Gorozdos, S.G. and P. J. Moran, "Using Electrochemical Impedance Spectroscopy to Determine Corroding Areas of Underground Steel Structures" Presented at the October Meeting of the Electrochemical Society, Honolulu, Hawaii (Oct 1987).
- 6. Murray, J.N., Ph. D. Dissertation, The Johns Hopkins University,
 Corrosion and Electrochemistry Research Laboratory (1988).
- Juttner, K., W.J. Lorenz, M.W. Kendig and F. Mansfeld,
 J. Electrochem. Soc., 135, No. 2, pp. 332-339 (1988).
- 8. Juttner, K. and W.J. Lorenz, In Proceedings of the Symposium on Computer Aided Acquisition and Analysis of Corrosion Data, <u>Electrochem. Soc. Proc.</u>, Vol. 85-3, M.W. Kendig, U. Bertocci, J.E. Strutt, eds., p. 75 (1985).
- 9. Scully, J.R., "Electrochemical Impedance Spectroscopy for Evaluation of Organic Coating Deterioration and Underfilm Corrosion-- A State of the Art Technical Review" David Taylor Research Center SME 86/006 (Sep 1986).

- 10. Scully, J.R., "Electrochemical Impedance of Organic-Coated Steel: Correlation of Impedance Parameters with Long-Term Coating Deterioration", <u>Journal of the Electrochemical Society</u>, Vol. 136, No 4, pp 979-990 (Apr 1989).
- 11. Mansfeld, F. and M. Kendig, "Evaluation of Protective Coatings with Impedance Measurements," Presented at the International Congress on Metallic Corrosion, Toronto, Canada, Sponored by The National Research Council Canada, 3, p. 74 (Jun 1984).
- 12. Mansfeld, F., M. Kendig and S. Tsai, <u>Corrosion Science</u>, <u>33</u>, No. 4, pp.317-329 (1983).
- 13. Haruyama, S., M. Asari and T. Tsuru, In <u>Proceedings of the Symposium on Corrosion Protection by Organic Coatings</u>, <u>Electrochem. Soc.</u>

 <u>Proc.</u>, Vol. 87-2, M. Kendig, H. Leidheiser, Eds. p. 197 (1987).
- 14. Murray, J. and P. Moran, "An EIS Study of the Corrosion Behavior of Polyethylene Coating Holidays in Natural Soil Conditions,"

 Corrosion, in press.
- 15. ASTM Standard D-823, <u>1986 ASTM Annual Book of Standards</u>, Vol. 06.01 (1986).
- 16. ASTM Standard D-610, <u>1986 ASTM Annual Book of Standards</u>, Vol. 06.01 (1986).
- 17. ASTM Standard D-714, <u>1986 ASTM Annual Book of Standards</u>, Vol. 06.01 (1986).

INITIAL DISTRIBUTION

Copies

- 1 DARPA 1400 Wilson Blvd. Arlington, VA 22209 Attn: Dr. P. Parrish
- 2 Commander Naval Surface Weapons Center Silver Spring, MD 20910 Attn: Dr. C. Dacres (Code R33) Dr. J. Tydings (Code R32)
- 1 Commander Naval Surface Weapons Center Dahlgren, VA 22448 Attn: Dr. Bettadapur (Code C53)
- 3 Commander
 Naval Civil Engineering Lab
 Port Hueneme, CA 93043
 Attn: Dr. R. Drisko,
 Mr. D. Zarate
 Mr. J. Jenkins
- 2 Department of the Army AMTL SLCHT-MCM-SB Watertown, MA 02172 Attn: Mr. M. Levy Dr. E. Wright
- 2 U.S. Army Research Office Associate Director of Metallurgy & Materials Science Division P.O. Box 1221 Triangle Park, NC 27709 Attn: Dr. John Hurt Dr. Robert Rebar
- 1 Commander Naval Ocean Systems Center San Diego, CA 92152 Attn: Mr. Gordon Chase (Code 932)
- 12 Defense Technical Information Ctr Cameron Station Alexandria, VA 22314

Copies

- 3 Commanding Officer
 Air Force Materials Laboratory
 Wright-Patterson AFB
 Dayton, OH 45433
 Attn: Mr. F. Meyer (Code MLSA)
- 1 Air Force Office of Scientific Research Bolling Air Force Base Washington, DC 20332 Attn: Dr. A. Rosenstein
 - 1 Naval Research Laboratory Dr. E. McCafferty (Code 6310)
 - 2 Office of Naval Research
 800 N. Quincy Street
 Arlington, VA 22217
 Attn: Dr. A. Sedriks (Code 1131)
 Dr. S. Fishman (Code 1131)
 - National Institute for Standards
 Technology
 Washington, DC 20234
 Attn: Dr. N.E. Pugh
 Dr. U. Bertocci
 - 1 Monsanto Company 800 N. Lindbergh Blvd. St. Louis, MO 63167 Attn: Dr. David Silverman
 - 1 Electrical Technology Corp. 1601 Dexter Avenue N. Seattle, WA 98109 Attn: Dr. Theodore Beck
 - 1 Center for Surface and Coating Research Sinclair Laboratory 7 Lehigh University Bethlehem, PA 18015 Attn: Dr. Richard Granata Dr. H. Leidheiser

Copies

- 2 EG&G Princeton Applied Research Copies P.O. Box 25651 Princeton, NJ 08540 Attn: Mr. Marc Rothstein Mr. Bill Eggers
- 1 Martin Marietta Laboratories 1450 South Rolling Road Baltimore, MD 21227-3898 Attn: Dr. W. Moshier
- 1 University of Nevada Reno, NV 89557 Attn: Dr. Denny Jones
- 1 Steel Structures Painting Council 4400 Fifth Avenue Pittsburgh, PA 15213 Attn: Dr. Bernard Appleman
- 2 The Johns Hopkins University Corrosion & Electrochemistry Research Center Charles and 34th Streets Baltimore, MD 21218 Attn: Dr. J. Kruger Dr. P.J. Moran

CENTER DISTRIBUTION

- 1 OlR (Moran)
- 1 0115 (Caplan)
- 1 28
- 1 2801 (Crisci)
- 1 2801 (Ventriglio)
- 1 2802 (Morton)
- 1 2803 (Cavallaro)
- 1 2809 (Malec)
- 5 281 (Gudas)
 - 5 2813 (Ferrara)
 - 10 2813 (Hack)
 - 3 2813 (Murray)
 - 1 2814 (Montemarano)
 - 1 283 (Singerman)
 - 1 284 (Fischer)
 - 5 2841 (Montemarano/Ross/ Laster/Loeb/Mihm)
 - 1 522.2 (TIC)
 - 2 5231 (Office Services)